

IMPORTANT SAFETY NOTICE

Tim Hortons Home 10-Cup Coffee Brewers Models GR-10W & B-10B Manufactured by Bunn-O-Matic



GR-10W



B-10B

**Sold approximately between February 2001 and
January 2005**

The plastic pour-in bowl can melt or ignite due to an electrical failure,
creating a burn and fire hazard

If you have one of these models, stop using it immediately. Unplug the unit and let it cool at least three hours before calling Bunn-O-Matic to determine if your model is included in the recall:

1-800-385-2652

7:00 am to 6:00 pm CT, Monday through Friday, or at:

www.regcen.com/bunnrecall

Bunn-O-Matic will repair your coffeemaker free of charge, provide you with a free in-home repair kit or offer a discount on a new replacement unit