

IMPORTANT SAFETY NOTICE

Attention ALL Tim Hortons Bunn Home Brewer Owners



GR-10W



B-10B

Bunn Home Brewer Repair Recall Program

Bunn-O-Matic has issued a voluntary North American wide recall of some of its coffee makers so that affected brewers can be repaired. This recall notice applies to all Tim Hortons Bunn Home Brewers sold between February 2001 to August 2004.

Bunn-O-Matic has informed us of a manufacturing defect which may result in the plastic pour-in bowl melting or igniting due to an electrical failure, creating a burn and fire hazard.

At Tim Hortons, we value our customers' safety above anything else. If you have one of these models or wish to find out if you do, stop using the model immediately. Unplug the unit and let it cool for at least 3 hours as the water inside the tank is extremely hot and you will be asked to empty the brewer to look at a model number on the bottom of the machine. Once the unit is cool, call the Bunn-O-Matic hotline at **1-800-385-2652**. You can also go to www.regcen.com/bunnrecall for more information.

If your Home Brewer is included in this recall, this is what will happen:

- Bunn will ship you a box with a pre-paid shipping address slip.
- Fill out the shipping address slip and place the brewer in the box.
- Take the box to your nearest Tim Hortons or UPS Depot for shipping.
- You will receive \$5 in gift certificates when the brewer is returned to a Tim Hortons store only.
- Bunn will repair your brewer.
- Bunn will ship the brewer back to the mailing address you used on the shipping invoice.
- You can expect your brewer back in approximately 5 business days.

We apologize for any inconvenience this may cause. Once again, please call **1-800-385-2652** to determine if your Tim Hortons Bunn Home Brewer is included in this recall.

Thank you for your understanding and continued loyalty.

Tim Hortons.